

Vacuum Products Division

RoHS C€

Model RGC-100 Series Digital Vacuum Gauge

RGC-100 Ranges .001 to 760 Torr .001 to 991 millibar INSTALLATION AND OPERATION MANUAL

Manual No. RGC100M Revision A May 2010

Warranty

Products manufactured by Seller are warranted against defects in materials and workmanship for twelve (12) months from date of shipment thereof to Customer, and Seller's liability under valid warranty claims is limited, at the option of Seller, to repair, to replace, or refund of an equitable portion of the purchase price of the Product. Items expendable in normal use are not covered by this warranty. All warranty replacement or repair of parts shall be limited to equipment malfunctions which, in the sole opinion of Seller, are due or traceable to defects in original materials or workmanship. All obligations of Seller under this warranty shall cease in the event of abuse, accident, alteration, misuse, or neglect of the equipment. In-warranty repaired or replaced parts are warranted only for the remaining unexpired portion of the original warranty period applicable to the repaired or replaced parts. After expiration of the applicable warranty period, Customer shall be charged at the then current prices for parts, labor, and transportation.


Reasonable care must be used to avoid hazards. Seller expressly disclaims responsibility for loss or damage caused by use of its Products other than in accordance with proper operating procedures.

Except as stated herein, Seller makes no warranty, express or implied (either in fact or by operation of law), statutory or otherwise; and, except as stated herein, Seller shall have no liability under any warranty, express or implied (either in fact or by operation of law), statutory or otherwise. Statements made by any person, including representatives of Seller, which are inconsistent or in conflict with the terms of this warranty shall not be binding upon Seller unless reduced to writing and approved by an officer of Seller.

Warranty Replacement and Adjustment


All claims under warranty must be made promptly after occurrence of circumstances giving rise thereto, and must be received within the applicable warranty period by Seller or its authorized representative. Such claims should include the Product serial number, the date of shipment, and a full description of the circumstances giving rise to the claim. Before any Products are returned for repair and/or adjustment, written authorization from Seller or its authorized representative for the return and instructions as to how and where these Products should be returned must be obtained. Any Product returned to Seller for examination shall be prepaid via the means of transportation indicated as acceptable by Seller. Seller reserves the right to reject any warranty claim not promptly reported and any warranty claim on any item that has been altered or has been returned by non-acceptable means of transportation. When any Product is returned for examination and inspection, or for any other reason, Customer shall be responsible for all damage resulting from improper packing or handling, and for loss in transit, notwithstanding any defect or non-conformity in the Product. In all cases, Seller has the sole responsibility for determining the cause and nature of failure, and Seller's determination with regard thereto shall be final.

If it is found that Seller's Product has been returned without cause and is still serviceable, Customer will be notified and the Product returned at Customer's expense; in addition, a charge for testing and examination may be made on Products so returned. 3/1/00



Contents

Description and Principle Of Operation	
Construction	1
Unpacking and Inspection	2
Installation	2
Operation	4
Servicing and Maintenance	6
Gauge Tube Servicing	6
Maintenance	
Factory Repair and Calibration	6
Field Calibration	6
Notes on Calibration	7
Understanding Torr	8
Accessories and Modifications	
Special Requirements	
Specifications	0



Declaration of Conformity Konformitätserklärung Déclaration de Conformité Declaración de Conformidad Verklaring de Overeenstemming Dichiarazione di Conformità



We

Wir Agilent, Inc.

Nous 121 Hartwell Avenue

Nosotros Lexington, MA, 02421-3133 USA

Wij Noi

declare under our sole responsibility that the product, erklären, in alleniniger Verantwortung, daß dieses Produkt, déclarons sous notre seule responsabilité que le produit, declaramos, bajo nuestra sola responsabilidad, que el producto, verklaren onder onze verantwoordelijkheid, dat het product, dichiariamo sotto nostra unica responsabilità, che il prodotto,

Model RGC-100 Series Digital Vacuum Gauge

Croup 1 Class A ISM emission requirements

to which this declaration relates is in conformity with the following standard(s) or other normative documents. auf das sich diese Erklärung bezieht, mit der/den flogenden Norm(en) oder Richtlinie(n) übereinstimmt. auquel se réfère cette déclaration est conforme à la (auz) norme(s) ou au(x) document(s) normatif(s). al que se refiere esta declaración es conforme a la(s) norma(s) u otro(s) documento(s) normativo(s). waamaar deze verklaring verwijst, aan de volende norm(en) of richtlijn(en) beantwoodt. a cui se rifersce questa dichiarazione è conforme alla/e sequente/l norma/o documento/l normativo/i.

EN 55011 (1991)	Group 1 Class A 15M emission requirements
EN 61010-1 (1993)	Safety requirements for electrical equipment for measurement, control, and laboratory use incorporating Amendments Nos 1 and 2.
EN 61000-3-2 (2006)	Limits for harmonic current emissions (equipment input current up to and including 16A per phase).
EN 610000-3-3 (2005)	Limitation of voltage fluctuations and flicker in low-voltage supply systems for equipment with rated current up to and including 16A.
EN 61326 (1997/A1; 1998/A2; 2001/A3)	EMC requirements for Electrical equipment for measurement, control and laboratory use — General Use.
EN 61326 (1997/A1; 1998/A2; 2001/A3)	EMC requirements for Electrical equipment for measurement, control and laboratory use
EN 61000 - 4-2 (2001)	Electrostatic Discharge Immunity
EN 61000 - 4-4 (2004)	Electrical Fast Transient Immunity
EN 61000 - 4-5 (2005)	AC Lightning Surge Immunity

Gohn Ehmam

EN 55011 (1991)

Operations Manager

Agilent, Inc.

Vacuum Products Division

Lexington, Massachusetts, USA

John Ehmann

May 27, 2010

Preface

Hazard and Safety Information

This manual uses the following standard safety protocols:

WARNING



The warning messages are for attracting the attention of the operator to a particular procedure or practice which, if not followed correctly, could lead to serious injury.

CAUTION



The caution messages are displayed before procedures, which if not followed, could cause damage to the equipment.

NOTE



The notes contain important information.

This product must only be operated and maintained by trained personnel. Board installation/replacement requires a properly trained service technician.

Before operating or servicing equipment, read and thoroughly understand all operation/maintenance manuals provided by Agilent. Be aware of the hazards associated with this equipment, know how to recognize potentially hazardous conditions, and how to avoid them. Read carefully and strictly observe all cautions and warnings. The consequences of unskilled, improper, or careless operation of the equipment can be serious.

In addition, consult local, state, and national agencies regarding specific requirements and regulations. Address any safety, operation, and/or maintenance questions to your nearest Agilent office.

Description and Principle Of Operation

The Agilent RGC-100 series gauge is a compact digital vacuum sensing instrument. It uses a thermocouple gauge tube to sense vacuum and display the reading in either milliTorr or mbar. The Agilent Model RGC-100 can be panel mounted using the same cutout and hole mounting pattern of a traditional Agilent 801 pointer meter gauge.

Consult the Agilent website www.Agilent.com for information about other Agilent vacuum controllers and gauges.

The Agilent Model RGC-100 operates by measuring the temperature rise of an electrically heated thermocouple exposed to a vacuum. As vacuum increases, or more correctly, as absolute pressure decreases, fewer and fewer molecules of gas are available to cool the thermocouple. With fewer molecules in the vacuum space, the air temperature rises and the thermocouple gauge thus senses the vacuum. A precision reference inside the Agilent in conjunction with an integrated circuit amplifier controls the electrical excitation of the sensor filament. The voltage response of the thermocouple is piped through a CPU and is translated to the current vacuum reading.

Construction

The RGC-100 consists of the indicating and controlling instrument, the gauge tube, the gauge tube cable, AC power supply, and if so equipped also has interfaces for the two control connections, analog out, and RS232.

The gauge tube houses the various thermocouple sensing, heating and compensating elements and terminates in an octal connector. On this model, the connector wiring terminates at the instrument with a 6 position RJ24. Regulating circuitry in the Agilent provides proper current for gauge tube excitation, and thus compensates for resistance in the probe leads.

Unpacking and Inspection

Each RGC-100 comes with:

After the Agilent RGC-100 is received, carefully unpack and inspect it for damage during shipment and for completeness. In the event of a loss during shipment, immediately make a claim to the common carrier or the postal service, as applicable. The Agilent warranty pertains only to the instrument, and does not cover losses in shipping.

	Display controller
	AC Power supply with wire leads
	Gauge Tube Cable
	Agilent 531 gauge tube
	Mounting Hardware
If orde	ered with additional options, it also comes with:
	AC power supply with international adapters (instead of above)
	5V5T analog recorder terminal connector
	RS232 DB9 connector
	Terminal connector for U and L relays

Installation

Locate the instrument in a clean, dry environment for best results. The unit can be panel mounted with the hardware provided:

- 1. Remove the front panel of the gauge, leaving the aluminum spacers on the gauge printed circuit board.
- 2. Make a 2.66" circular mounting hole in the panel at the desired location.
- 3. Make 3 or 4 holes, 5/32" diameter (clearance holes for #4 screws) on a 1.58 radius from the center of the mounting hole. (The front panel that comes with the gauge can be used as a template.)
- 4. Reassemble the gauge, with the plastic panel outside, and the gauge behind.

Identify the gauge tube cable by wire tags or markings specific to your environment.

Thermocouple gauge tubes must be installed in a thread-down orientation in a clean, dry vacuum system. While threading the gauge tube in to the manifold, disconnect the gauge tube cable to avoid damage. In this way, twisting of the cable and the octal socket on the tube is avoided. Exercise care to install the tubes in a dry part of the system. Since the instrument works on the principle of temperature rise, the probes will not work if they become filled with a liquid such as vacuum or diffusion pump oil. Protect the gauge tube against oil and other contaminants by installing it in such a way to protect it. A good practice is to mount the gauge tube in the most vertically distant place from oil and other contaminants as applicable. Mount the gauge tube in the most stable pressure region of the vessel to be measured. For example, it would be better to install the gauge tube on a tank rather than on the pipe that is directly connected to a vacuum pump. In the event of contamination, see section 6.0 for gauge tube cleaning instructions.

If the gauge is used in a Neon sign processing facility, the following is recommended to protect the gauge from bombarding damage:

- □ Isolate the gauge tube from the system with a stopcock. Close the stopcock closed when bombarding.
- ☐ There must be at least two (2) feet of tubing between the electrode and the Instrument. For best results, use metal tubing.
- ☐ In extreme cases, the gauge can be absolutely protected by installing a normally open solenoid valve between the gauge tube and the system. Ensure the solenoid valve coil is in parallel with the bombarding transformer. In this way, the solenoid is closed and the gauge tube is positively protected whenever bombarding is done.
- ☐ If a gauge is damaged by bombarding, it can generally be brought back to operating condition by replacing the Op amp which controls the gauge tube current. Consult Agilent.



Figure 1 Card Interface Connections

The set point connections are in the back of the unit. There is one row of pins with a terminal strip connector for the two (2) set point connections. The set point connections are in the order:

1. Common The common line of a switch.

2. N.C. Normally closed. This means that above the set point value there is

a current path between the common and the N.C. terminal. Put another way the switch is *ON* between these 2 terminals. At the set point value and below (higher vacuum, lower pressure) the connection is open. Put another way, the switch is *OFF* between the common and the N.C. connection at higher vacuum (a lower pres-

sure reading).

3. N.O. Normally open. This means that above the set point value there is

no current path between the common and N.O. connection. Put another way the switch is *OFF* between these 2 terminals. When the vacuum indication goes below the set point value (higher vacuum, lower pressure) the current path closes. Put another way the switch is *ON* between the common and N.O. connections at abso-

lute pressure readings below the set point value.

Take care to insure that the wire connections are made fast, and the voltage and current does not exceed 250V or 7A. If you need to control a device that draws more power, consider another relay in between the unit output and the device to be controlled

The Analog output is located in the center of the back panel, and must be connected to a high impedance input. The output impedance is 1K.

The RS232 connection can be made to a PLC or computer via a male DB9 cable connection to the female DB9 connection on the unit. The Agilent acts as a DCE, so a straight serial connection is appropriate.

Use the supplied 5V AC adapter with your Instrument. This adapter provides clean short protected power to protect and insure proper functioning of the internal circuitry.

Operation

After installation, the Instrument is ready for immediate operation. The unit normally provides accurate readings immediately however, occasionally a gauge tube absorbs material during storage, and may require as much as 24 hours of operation before accurate readings are attained. It is recommended that the Agilent AGC-100 be energized continuously during vacuum system operation. In this way, the hot filament does not allow contaminants to condense.

In cases where the system has contaminants, as is often the case with metalizing and coating equipment, it is often effective to isolate the gauge tube with a solenoid or manual valve during periods when contamination is most active.

The Agilent RGC-100 has two set points to actuate external equipment. These two set points can be adjusted from the front of the gauge in your currently selected units:




Figure 2 Card Adjustment Buttons

- 1. Change SP1 by:
 - a. Pressing the **U** button (Figure 2) set point 1 appears.
 - b. Turning the *SP1* or the left most potentiometer when looking at the front face of the RGC-100 to adjust set point 1 to the desired level.
- 2. Change SP2 by:
 - a. Pressing the **L** button- set point 2 appears.
 - b. Turning the *SP2* or the right most potentiometer when looking at the front face of the RGC-100 to adjust set point 2 to the desired level.
- 3. If you don't want the set points to actuate at all, set the set point for 000.

The instrument has additional outputs:

RS232 The instrument puts out a standard RS232 serial stream with settings 9600, 8, N, and 1. The unit transmits but does not receive,

and displays the current vacuum indication in the current units.

Analog out This output reads from 0 to 5 Volts from a pressure of 1 micron all

the way up to 5 Torr. There is a graduation of 1 milliVolt per milli-Torr. Therefore, 10 milliVolts = 10 milliTorr, and 4 Volts = 4 Torr.

Servicing and Maintenance

Gauge Tube Servicing

In many cases, a gauge tube may become fouled with oil or other foreign matter. It is often possible to restore the functionality of contaminated probes with cleaning. If the contaminant is known, fill the tube with a fluid that is known to be a solvent to that contaminant. As an example, ether is often effective in removing residues of some oils. Commercial carburetor cleaners are very powerful solvents and are highly effective against some contaminants.

After cleaning with solvents, completely dry or flush the gauge tube with a volatile solvent to assure that it is dry prior to re-installing it. If this is not done, contamination of the system may result.

Maintenance

Your vacuum instrument should give you many years of trouble free service. There are no regularly scheduled maintenance intervals. If consistent accuracy is required, it is recommended that the gauge, tube, cable and power supply be returned for a yearly calibration check.

Factory Repair and Calibration

The vacuum gauge assembly is designed to provide years of trouble-free service, and the liberal internal use of plug-in components make it easily repairable. No field servicing of the unit is recommended, other than replacement of the gauge tube, but factory servicing and calibration are available at a nominal cost and fast turn-around times.

Field Calibration

Each Agilent vacuum gauge controller is calibrated to the particular vacuum gauge sensor that is shipped with the unit. While changing the gauge tube is possible, it results in a slightly different reading as all gauge tubes are not created equal. Although it is preferable that all calibration be performed at Agilent, field calibration can be accomplished.

Before re-calibrating the instrument, ascertain if the instrument is in fact incorrect. In many cases, the problem is with a fouled tube, or a system that is operating improperly. It is recommended that a spare tube be kept on hand and stored in a clean, dry place. Then, in cases of suspect readings, change the tube before proceeding further.

If adjustments are to be made, proceed as follows:

1. Remove the instrument from the panel.

The *Zero* potentiometer is at the top center just below the top mounting hole as you look at the LED Display, the *ATM* or span adjust is to the left on the back of the board on the same side as the sensor RJ connector.

- 2. Operate the vacuum system at the lowest attainable pressure, and allow the system and the gauge tube to stabilize for several minutes. Factory zero setting is done at a pressure of .1 milliTorr (.1 micron) or less.
- 3. Adjust the zero setting potentiometer so the unit reads zero. Make sure not to under span. Allow the measurement standard to rise to 1 milliTorr and make sure the gauge reading also reads 1 milliTorr.
- 4. Check the operation of the gauge at other pressures. Normally, slight adjustments of the zero will not be interactive with the readings of the instrument at higher pressures.

The ATM adjustment is normally not necessary. If necessary, adjust the span with the ATM potentiometer:

- 1. Set the vacuum level to Atmosphere (approximately 760 Torr) and slowly turn the potentiometer on the right until the Agilent gauge reads 760 Torr, being careful not to over span.
- 2. If you adjust the span, recheck the zero, then the span, and the zero one last time.

Notes on Calibration

The instrument is calibrated in nitrogen, which has thermal properties virtually identical to air. Other gasses affect the readings by an amount proportional to the thermal conductivity of the gases. In most cases, the gases present in a vacuum system are air, nitrogen, or oxygen, and no appreciable errors occur.

Certain other gases, however, have thermal conductivity significantly greater than air and cause the instrument to read higher than the actual amount of pressure. Examples of such gasses are water vapor, fluorocarbon refrigerants, and acetone. Conversely, other gasses have thermal conductivity significantly lower than air and cause the instrument to read lower than actual pressure. Examples of such gasses include helium, oxygen and to a lesser extent, CO₂.

When interpreting readings using gasses other than air, remember that the Agilent AGC-100 reads Torr, which is a measure of absolute pressure - that is the opposite of vacuum. Thus, a lower numerical reading actually is a higher level of vacuum. For more information, refer to "Understanding Torr" on page 8. When in doubt, consult Agilent.

Understanding Torr

The Agilent AGC-100 and many similar instruments are calibrated in microns or *milliTorr*. It is appropriate to discuss what microns are and to relate microns to other measures of pressure and vacuum. Microns are not really a measure of vacuum at all, but rather of absolute pressure. The pressure of the atmosphere is 14.696 or approximately 14.7 pounds per square inch at sea level. This pressure is due to the weight of all of the air in the earth's atmosphere above any particular square inch. This 14.696 psi is equivalent to the pressure produced by a mercury column of approximately 29.92 inches high or .76 meters (about 3/4 of a yard) or 760 millimeters of mercury. Atmospheric pressure varies greatly with altitude. It decreases approximately 1 inch of mercury per thousand feet of altitude. It also varies widely with local weather conditions. (Variations of one half inch in a single day are common.) The word vacuum means pressure lower than atmospheric or *suction*, but, in describing negative pressure, the atmosphere is only a satisfactory reference if we are dealing with values of vacuum down to about 27 inches of mercury. Below that, it is much more useful to talk in terms of absolute pressure, starting from absolute zero. The RGC-150 and all similar instruments do just this.

One TORR, a commonly used unit, is an absolute pressure of one millimeter of mercury. A milliTorr is equal to one thousandth of a TORR. A MICRON is the same as a milliTorr.

Accessories and Modifications

Consult the product guide and website for the latest available accessories. We also offer analog output, RS232 and two (2) set point controls as production options to the RGC-100.

Special Requirements

It is the policy of the Agilent Company to customize instruments for specialized requirements whenever it is economically feasible to do so. We encourage inquiries about your special needs.

Specifications

Table 2-1 Specifications

Specification	Definition
Input Voltage	0.5 A at 5 VDC
Maximum Relay Voltage and Current	250 VAC at 7 Amps
Recommended wire gauge for analog and set point wiring	14-28 AWG
Maintenance Interval	1-10 years depending on use
Overall Dimensions	4.0 in wide, 3.5 in high, 5.65 in deep
Panel Cutout Dimensions	2.66 inch diameter cutout
Ambient Operating range	0°C to 70°C
Measurement Media	Clean Dry Air or Nitrogen

CAUTION

There may be impairment to the protection of the equipment if it is used in a manner that is not specified.



Table 2-2 Instrument Accuracy

Range	Accuracy
.001 to .010 Torr	+/001 Torr
.010 to 2.00 Torr	+/- 15% of reading
2.0 to 160 Torr	+/- 50% of reading
160 to 760 Torr	+/- 25% of reading

For repair or recalibration, return gauges to:

Agilent Lexington, MA 02421-3133 Ph:1.800.882.7426 www.agilent.com

E-mail: Direct from our website www.agilent.com

Agilent manufactures a complete line of vacuum gauges and process computers. Contact us or your distributor if you need further information.



Vacuum Products Division Instructions for returning products

Dear Customer:

Please follow these instructions whenever one of our products needs to be returned.

- 1) Complete the attached Request for Return form and send it to Agilent Technologies (see below), taking particular care to identify all products that have pumped or been exposed to any toxic or hazardous materials.
- 2) After evaluating the information, Agilent Technologies will provide you with a Return Authorization (RA) number via email or fax, as requested.

Note: Depending on the type of return, a Purchase Order may be required at the time the Request for Return is submitted. We will quote any necessary services (evaluation, repair, special cleaning, eg).

- 3) Important steps for the shipment of returning product:
 - Remove all accessories from the core product (e.g. inlet screens, vent valves).
 - Prior to shipment, drain any oils or other liquids, purge or flush all gasses, and wipe off any excess residue.
 - If ordering an Advance Exchange product, <u>please use the packaging from the Advance Exchange to return the defective</u> product.
 - Seal the product in a plastic bag, and package product carefully to avoid damage in transit. You are responsible for loss or damage in transit.
 - Agilent Technologies is not responsible for returning customer provided packaging or containers.
 - Clearly label package with RA number. Using the shipping label provided will ensure the proper address and RA number
 are on the package. Packages shipped to Agilent without a RA clearly written on the outside cannot be accepted and will
 be returned.
- 4) Return only products for which the RA was issued.
- 5) Product being returned under a RA must be received within 15 business days.
- 6) Ship to the location specified on the printable label, which will be sent, along with the RA number, as soon as we have received all of the required information. Customer is responsible for freight charges on returning product.
- 7) Return shipments must comply with all applicable **Shipping Regulations** (IATA, DOT, etc.) and carrier requirements.

RETURN THE COMPLETED **REQUEST FOR RETURN** FORM TO YOUR NEAREST LOCATION:

 Fax:
 00 39 011 9979 330

 Fax Free:
 00 800 345 345 00
 Fax:
 1 781 860 9252
 please visit our website for individual office information

 Toll Free:
 00 800 234 234 00
 Toll Free: 800 882 7426, Option 3
 office information

 vpt-customercare@agilent.com
 vpl-ra@agilent.com
 http://www.agilent.com



Vacuum Products Division Request for Return Form (Health and Safety Certification)

Please read important policy information on Page 3 that applies to all returns.

Company Name:	ATION			
oumpany Ivaine.			Contact Name:	
Tel:		Email:	Fax:	
Customer Ship To:			Customer Bill To:	
Europe only: VAT re	g. Number:		USA/Canada only: Tax	able Non-taxable
) PRODUCT IDENTIFICA	ATION			
Product Description		Agilent P/N	Agilent S/N	Original Purchasing Reference
RADIOACTIVE MATER Call Agilent Technolo The equipment listed HAS I	RIAL, OR MER ogies to discus above (check NOT pumped o pumped or be	CURY AT ITS FACILITY. ss alternatives if this re k one): or been exposed to any t	rts contaminated with Biolog quirement presents a problem. toxic or hazardous materials. OR ving toxic or hazardous materials. If	
	nation must a		boxes for all materials to which prod	
inform	nation must a Corrosive	lso be filled out. Check	boxes for all materials to which prod	_
inform	Corrosive	Iso be filled out. Check Reactive Flag	boxes for all materials to which prod	duct(s) pumped or was exposed: Biological Radioactive
inform Toxic C List all toxic/hazardo NOTE: If a product is receive	Corrosive ous materials. red at Agilent whi e safe handling o	Iso be filled out. Check Reactive Flat Include product name, ich is contaminated with a toxi of the product, and is liable for esent in the product.	boxes for all materials to which proc ammable Explosive Chemical name, and chemical sym	duct(s) pumped or was exposed: Biological Radioactive bol or formula: ed, the customer will be held responsible for a
Inform Toxic (List all toxic/hazardo NOTE: If a product is receive costs incurred to ensure the exposure to toxic or hazardo Print Name:	Corrosive ous materials. red at Agilent whi e safe handling o ous materials pre	Iso be filled out. Check Reactive Flat Include product name, ich is contaminated with a toxi of the product, and is liable for esent in the product.	boxes for all materials to which proc ammable Explosive Chemical name, and chemical sym ic or hazardous material that was not disclose any harm or injury to Agilent employees as w	duct(s) pumped or was exposed: Biological Radioactive bol or formula: ed, the customer will be held responsible for all yell as to any third party occurring as a result of
Inform Toxic () List all toxic/hazardo NOTE: If a product is receive costs incurred to ensure the exposure to toxic or hazardo Print Name: FAILURE INFORMATION	Corrosive Dus materials. Tred at Agilent whi e safe handling o oous materials pre	Reactive Flater	boxes for all materials to which proc ammable Explosive Chemical name, and chemical symic or hazardous material that was not disclose any harm or injury to Agilent employees as weature:	duct(s) pumped or was exposed: Biological Radioactive bol or formula: ed, the customer will be held responsible for all yell as to any third party occurring as a result of
Inform Toxic	Corrosive pus materials. red at Agilent whi e safe handling o ous materials pre ION: RED FIELD. Se	Iso be filled out. Check Reactive Flat. Include product name, ich is contaminated with a toxion of the product, and is liable for esent in the product. Authorized Signate next page for suggest	boxes for all materials to which proc ammable Explosive Chemical name, and chemical symic or hazardous material that was not disclose any harm or injury to Agilent employees as we mature:	duct(s) pumped or was exposed: Biological Radioactive bol or formula: ed, the customer will be held responsible for a vell as to any third party occurring as a result of
Inform Toxic	Corrosive pus materials. red at Agilent whi e safe handling o ous materials pre ION: RED FIELD. Se of Malfunction	Reactive Flater	boxes for all materials to which proc ammable Explosive Chemical name, and chemical symic or hazardous material that was not disclose any harm or injury to Agilent employees as we mature:	duct(s) pumped or was exposed: Biological Radioactive bol or formula: ed, the customer will be held responsible for all yell as to any third party occurring as a result of



Vacuum Products Division Request for Return Form (Health and Safety Certification)

Please use these Failure Mode to describe the concern about the product on Page 2.

TURBO PUMPS and TURBO CONTROLLERS

APPARENT DEFECT/MALFUNCT	ΓΙΟΝ	POSITION	PARAMETERS	
- Does not start	- Noise	- Vertical	Power:	Rotational Speed:
- Does not spin freely	- Vibrations	-Horizontal	Current:	Inlet Pressure:
- Does not reach full speed	-Leak	-Upside-down	Temp 1:	Foreline Pressure:
- Mechanical Contact	-Overtemperature	-Other:	Temp 2:	Purge flow:
- Cooling defective	-Clogging		OPERATING TI	ME:

ION PUMPS/CONTROLLERS

- Bad feedthrough	- Poor vacuum
- Vacuum leak	- High voltage problem
- Error code on display	- Other

LEAK DETECTORS

- Cannot calibrate	-No zero/high backround
- Vacuum system unstable	- Cannot reach test mode
- Failed to start	- Other

SCROLL AND ROTARY VANE PUMPS

_		
	- Pump seized	- Other
	- Doesn't reach vacuum	- Over temperature
	- Pump doesn't start	 Noisy pump (describe)

VALVES/COMPONENTS

- Main seal leak	- Bellows leak
- Solenoid failure	- Damaged flange
- Damaged sealing area	-Other

INSTRUMENTS

- Gauge tube not working	- Display problem
- Communication failure	- Degas not working
- Error code on display	- Other


DIFFUSION PUMPS

- Heater failure	- Electrical problem
- Doesn't reach vacuum	- Cooling coil damage
- Vacuum leak	- Other

Section 6) ADDITIONAL TERMS

Please read the terms and conditions below as they apply to all returns and are in addition to the Agilent Technologies Vacuum Product Division — Products and Services Terms of Sale.

- Customer is responsible for the freight charges for the returning product. Return shipments must comply with all
 applicable Shipping Regulations (IATA, DOT, etc.) and carrier requirements.
- Customers receiving an Advance Exchange product agree to return the defective, rebuildable part to Agilent Technologies
 within 15 business days. Failure to do so, or returning a non-rebuildable part (crashed), will result in an invoice for the
 non-returned/non-rebuildable part.
- Returns for credit toward the purchase of new or refurbished Products are subject to prior Agilent approval and may incur
 a restocking fee. Please reference the original purchase order number.
- Units returned for evaluation will be evaluated, and a quote for repair will be issued. If you choose to have the unit
 repaired, the cost of the evaluation will be deducted from the final repair pricing. A Purchase Order for the final repair price
 should be issued within 3 weeks of quotation date. Units without a Purchase Order for repair will be returned to the
 customer, and the evaluation fee will be invoiced.
- A Special Cleaning fee will apply to all exposed products per Section 4 of this document.
- If requesting a calibration service, units must be functionally capable of being calibrated.



Agilent Technologies

Vacuum Product Division

United States & Canada

Agilent Technologies Vacuum Products Division 121 Hartwell Avenue Lexington, MA 02421 USA Tel: +1 781 861 7200 Toll-Free: +1 800 882 7426

Fax: +1 871 860 5437

Benelux

Agilent Technologies
Vacuum Products Division
Herculesweg 8
4338 PL Middelburg
THE NETHERLANDS
Tel: +31 118 671570
Fax: +31 118 671569

China

Agilent Technologies
Vacuum Products Division
Room 1648
Central Tower South Wing
Beijing Junefield Plaza
No. 10 XuanWuMenWai Street
Beijing 100052 P.R. CHINA
Tel.: +86 (10) 6310 8550
Toll-Free: 800 820 6556
Fax: +86 (10) 6310 0141

France

Agilent Technologies
Vacuum Products Division
7 avenue des Tropiques
Z.A. de Courtaboeuf - B.P. 12
91941 Les Ulis cedex FRANCE
Tel.: +33 (0) 1 69 86 38 84
Fax: +33 (0) 1 69 86 29 88

Germany & Austria

Agilent Technologies Vacuum Products Division Alsfelder Strasse 6 Postfach 11 14 35 64289 Darmstadt GERMANY Tel.: +49 (0) 6151 703 353

Fax: +49 (0) 6151 703 302

India

Agilent Technologies Vacuum Product Division 205-A, "A" wing of Galleria, 2nd floor, Hiranandani Gardens, Powai, Mumbai-400 076, India Tel.: +91 22-2570 8595 / 8597 Fax: +91 22- 2570 8599

Italy

Agilent Technologies
Vacuum Products Division
via F.Ili Varian 54
10040 Leini, (Torino) ITALY
Tel.: +39 011 997 9111
Toll-Free: 00 800 234 234 00
Fax: +39 011 997 9350

Japan

Agilent Technologies
Vacuum Products Division
Sumitomo Shibaura Building 4-16-36
8th Floor
4-16-36 Shibaura Minato-ku
Tokyo 108 JAPAN
Tel.: +81 3 5232 1253
Toll-Free: 0120 655 040
Fax: +81 3 5232 1710

Korea

Agilent Technologies
Vacuum Products Division
Shinsa 2nd Bldg. 2F 966-5
Daechi-dong
Kangnam-gu, Seoul
KOREA 135-280
Tel.: +82 2 3452 2452
Toll-Free: 080 222 2452
Fax: +82 2 3452 2451

Mexico

Agilent Technologies Vacuum Products Division Concepcion Beistegui No 109 Col Del Valle C.P. 03100 MEXICO, D.F.

Tel.: +52 5 523 9465 Fax: +52 5 523 9472

Southeast Asia

Agilent Technologies Vacuum Products Division South East Asia (SEA) - Alex Ho H/P: +601 2213 1253 Fax: +603 6733 8121

Singapore

Agilent Technologies Vacuum Products Division Singapore Unit 10-04 Helios Biopolis @ one-north 11 Biopolis Way, 138667 Singapore

H/P.: +65 92364988 Fax: +65 64789603

Taiwan

Agilent Technologies Vacuum Products Division 14F-6, No. 77, Hsin Tai Wu Road, Sec. 1 Hsi chih, Taipei Hsien, Taiwan, R.O.C.

Tel.: +886 2 2698 9555 Toll Free: 0800 051 342 Fax: +886 2 2698 9678

UK & Ireland

Agilent Technologies Vacuum Products Division 6 Mead Road Oxford Industrial Park Tel.: +44 (0) 1865 291570

Fax: +44 (0) 1865 291571





