

Support \ Compatibility Matrix

UV/Vis ChemStation Revisions A.02.0x→A.10.0x

	A.02.0x	A.05.0x	A.06.0x	A.07.0x	A.08.0x	A.09.0x	A.10.0x
Windows® 3.1 / WFW® 3.11	Yes	No	No	No	No	No	No
Windows®95	Yes	Yes (7)	Yes	No	No	No	No
Windows® NT Workstation 4.0	No	Yes (7)	Yes	Yes	Yes	Yes	No
Service Pack 3	No	No	Yes(A.06.02 only)(10)	No	No	No	No
Service Pack 4	No	No	Yes(A.06.03/.04 only)	Yes (A.07.01 only)	No	No	No
Service Pack 5	No	No	No	No	No	No	No
Service Pack 6a	No	No	No	Yes	Yes	Yes	No
Windows® 98	No	No	No	No	No	No	No
Windows® ME	No	No	No	No	No	No	No
Windows®2000 Professional	No	No	No	No	No	Yes (4/6)	Yes (5/6)
Service Pack 2	No	No	No	No	No	Yes (4/6)	No
Service Pack 3	No	No	No	No	No	No	Yes (5/6)
Windows® XP	No	No	No	No	No	No	Yes (5/6)
Service Pack 1a	No	No	No	No	No	No	Yes (5/6)
LAN Communication	No	No	Yes	Yes	Yes	Yes	Yes
82335 GPIB Card (Windows® 3.1x and Windows® 95 only)	Yes	Yes (7)	Yes (Rev 82335I)	No	No	No	No
82341C GPIB Card (Not on Win® 3.1x)	No	Yes (7/8)	Yes	Yes (9)	Yes (2)	No	Yes
82341D GPIB Card (Not on Win® 3.1x)	No	Yes (7/8)	Yes	No	Yes (2)	No	No
82350A PCI GPIB Card (Only on Windows® NT/2000/XP)	No	No	No	Yes (3) (Rev H)	Yes (2)	No	Yes
82350B PCI GPIB Card	No	No	No	No	No	No	Yes
82350C PCI GPIB Card	No	No	No	No	No	Yes	No
GPIB I/O Lib Rev. F.01.00	No	Yes	No	No	No	No	No
GPIB I/O Lib Rev. F.01.02.00	No	No	Yes	No	No	No	No
GPIB I/O Lib Rev. G.02.02.01	No	No	No	Yes (9)	No	No	No
GPIB I/O Lib Rev. H.01.02.00	No	No	No	No	Yes (2)	No	No
Patch Rev H.01.03.71_beta	No	No	No	No	Yes (2)	No	No
GPIB I/O Lib Rev. J.02.01.00	No	No	No	No	No	No	No
GPIB I/O Lib Rev. K.01.00.00	No	No	No	No	No	Yes	No
GPIB I/O Lib Rev. L.02.01.00	No	No	No	No	No	No	Yes
G1115AA UV-VIS	Yes	Yes (1)	Yes	Yes	Yes	Yes (4/6)	Yes (5/6)
G1116AA UV-VIS	Yes	Yes (1)	Yes	Yes	Yes	Yes (4/6)	Yes (5/6)
G1117AA UV-VIS	Yes	Yes (1)	Yes	Yes	Yes	Yes (4/6)	Yes (5/6)
G1118AA UV-VIS	No	Yes (1)	Yes	Yes	Yes	Yes (4/6)	Yes (5/6)

This document is believed to be accurate and up-to-date. However, Agilent Technologies, Inc. cannot assume responsibility for the use of this material. The information contained herein is intended for use by informed individuals who can and must determine its fitness for their purpose. Windows®, Windows® 95, Windows® NT, Windows® 2000 Pro & ME, Windows® XP are registered trademarks of Microsoft Corp.

- | |
|---|
| (1) New Co-resident and Co-execution ChemStation Software was started with Revision A.05.02 and above |
| (2) Requires H.01.03.71 Beta Patch for PCI style 82350A card (on ChemStation CD in \Support\GPIB folder) for D9538N/D9538T PC's. |
| (3) 82350A Requires GPIB drivers from the A.07.0x or A.08.0X CD-ROM (\GPIB folder). The 82350B tested using GPIB driver revision L.02.01 only. |
| (4) UV/VIS ChemStation Rev. A.09.01 is supported on Windows® 2000 SP2, or Windows® NT4.0 SP6a. |
| (5) UV/VIS ChemStation Rev. A.10.01 is supported on Windows® 2000 SP3 and Windows® XP SP1a. |
| (6) UV/VIS ChemStation Revs $\geq$ A.09.01 supporting Windows® 2000 & XP are now on a separate CD-ROM's and will NO longer co-exist or co-execute with GC/LC/CE/AD/LCMS software. |
| (7) Rev A.05.02 supported the 82341 Rev C and D GPIB boards under Windows® NT4.0 and 82335 and 82341 Rev C and D GPIB boards under Windows® 95. |
| (8) With the HP8452A only the 82341 Rev D can be used. |
| (9) On Kayaks, if no communication is established on the 8452A or if "Power Fail" is seen on 8453A, replace 82341C board with 82341D and use the Rev H drivers. |
| (10) Rev A.06.01 is not a valid revision for UV-Vis ChemStation and must be upgraded to Rev A.06.02. |

This document is believed to be accurate and up-to-date. However, Agilent Technologies, Inc. cannot assume responsibility for the use of this material. The information contained herein is intended for use by informed individuals who can and must determine its fitness for their purpose. Windows®, Windows® 95, Windows® NT, Windows® 2000 Pro & ME, Windows® XP are registered trademarks of Microsoft Corp.