

Check Boxes

Site Preparation Specification

Purpose of Procedure

To assure that the installation of Agilent instruments and systems can be completed successfully by careful preparation and evaluation of the installation site and by ensuring the availability of appropriate utilities, consumables and supplies.

Customer Responsibilities

Customers should ensure that all necessary operating supplies, consumables and usage dependent items such as columns, vials, syringes and solvents required for the successful installation of instruments and systems are available.

Installation sites should be prepared in accordance with the following specifications.

Important Information

If you have problems in providing any of the following, please contact your local Agilent Technologies office for assistance. Assistance with user specific applications may be provided but should be contracted separately. Users of the instrument should be present throughout the installation and familiarization otherwise important operational, maintenance and safety information may be missed.

Procedure Checklist

Operating System Requirements

- Windows NT 4.0 with service pack 6 or higher or Windows 2000 with service pack 2 or higher
- Windows XP with service pack 1a
- User logon with Administrative capabilities
- ChemStation A.09.01 or higher A-versions for LC

Hardware Requirements for Windows NT

- Pentium II processor operating at 266 MHz or higher
- At least 96 MB of RAM
- CD-ROM drive
- Display: min. resolution 1024 x 768, more than 256 colors
- Microsoft Windows compatible pointing device

Hardware Requirements for Windows 2000 and Windows XP

Refer to the requirements for the ChemStation

Issued: January 2006 - Rev. 4.0 PN#: G2182-90110 WAD Product Support