

Section 2. Hazards identification

Classification of the substance or mixture

Not classified.

2.2 GHS label elements

Signal word	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No signal word.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No signal word.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	No signal word.
Hazard statements	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.

Precautionary statements

Prevention	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Not applicable.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Not applicable.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	Not applicable.
Response	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Not applicable.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Not applicable.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	Not applicable.
Storage	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Not applicable.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Not applicable.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	Not applicable.
Disposal	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Not applicable.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Not applicable.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	Not applicable.
Supplemental label elements	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	None known.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	None known.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	None known.

2.3 Other hazards

Hazards not otherwise classified	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	None known.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	None known.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	None known.

Section 3. Composition/information on ingredients

Substance/mixture	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Mixture
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Mixture
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	Mixture

Any concentration shown as a range is to protect confidentiality or is due to batch variation.

There are no ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

Occupational exposure limits, if available, are listed in Section 8.

Section 4. First aid measures

4.1 Description of necessary first aid measures

Eye contact	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Immediately flush eyes with plenty of water, occasionally lifting the upper and lower eyelids. Check for and remove any contact lenses. Get medical attention if irritation occurs.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Immediately flush eyes with plenty of water, occasionally lifting the upper and lower eyelids. Check for and remove any contact lenses. Get medical attention if irritation occurs.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	Immediately flush eyes with plenty of water, occasionally lifting the upper and lower eyelids. Check for and remove any contact lenses. Get medical attention if irritation occurs.
Inhalation	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Remove victim to fresh air and keep at rest in a position comfortable for breathing. Get medical attention if symptoms occur.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Remove victim to fresh air and keep at rest in a position comfortable for breathing. Get medical attention if symptoms occur.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	Remove victim to fresh air and keep at rest in a position comfortable for breathing. Get medical attention if symptoms occur.
Skin contact	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Flush contaminated skin with plenty of water. Remove contaminated clothing and shoes. Get medical attention if symptoms occur.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Flush contaminated skin with plenty of water. Remove contaminated clothing and shoes. Get medical attention if symptoms occur.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	Flush contaminated skin with plenty of water. Remove contaminated clothing and shoes. Get medical attention if symptoms occur.
Ingestion	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Wash out mouth with water. Remove victim to fresh air and keep at rest in a position comfortable for breathing. If material has been swallowed and the exposed person is conscious, give small quantities of water to drink. Do not induce vomiting unless directed to do so by medical personnel. Get medical attention if symptoms occur.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Wash out mouth with water. Remove victim to fresh air and keep at rest in a position comfortable for breathing. If material has been swallowed and the exposed person is conscious, give small quantities of water to drink. Do not induce vomiting

Section 4. First aid measures

SureGuide pSGLenti CRISPR
Control Plasmid (Human)

unless directed to do so by medical personnel. Get medical attention if symptoms occur.
Wash out mouth with water. Remove victim to fresh air and keep at rest in a position comfortable for breathing. If material has been swallowed and the exposed person is conscious, give small quantities of water to drink. Do not induce vomiting unless directed to do so by medical personnel. Get medical attention if symptoms occur.

4.2 Most important symptoms/effects, acute and delayed

Potential acute health effects

Eye contact	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.
Inhalation	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.
Skin contact	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.
Ingestion	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.

Over-exposure signs/symptoms

Eye contact	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No specific data.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No specific data.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No specific data.
Inhalation	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No specific data.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No specific data.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No specific data.
Skin contact	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No specific data.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No specific data.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No specific data.

Section 4. First aid measures

Ingestion	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No specific data.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No specific data.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No specific data.

4.3 Indication of immediate medical attention and special treatment needed, if necessary

Notes to physician	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.
Specific treatments	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No specific treatment.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No specific treatment.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No specific treatment.
Protection of first-aiders	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No action shall be taken involving any personal risk or without suitable training.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No action shall be taken involving any personal risk or without suitable training.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No action shall be taken involving any personal risk or without suitable training.

See toxicological information (Section 11)

Section 5. Fire-fighting measures

5.1 Extinguishing media

Suitable extinguishing media	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Use an extinguishing agent suitable for the surrounding fire.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Use an extinguishing agent suitable for the surrounding fire.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	Use an extinguishing agent suitable for the surrounding fire.
Unsuitable extinguishing media	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	None known.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	None known.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	None known.

5.2 Special hazards arising from the substance or mixture

Specific hazards arising from the chemical	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	In a fire or if heated, a pressure increase will occur and the container may burst.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	In a fire or if heated, a pressure increase will occur and the container may burst.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	In a fire or if heated, a pressure increase will occur and the container may burst.

Section 5. Fire-fighting measures

Hazardous thermal decomposition products	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No specific data.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No specific data.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	No specific data.

5.3 Advice for firefighters

Special protective actions for fire-fighters	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training.
Special protective equipment for fire-fighters	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

Section 6. Accidental release measures

6.1 Personal precautions, protective equipment and emergency procedures

For non-emergency personnel	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Put on appropriate personal protective equipment.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Put on appropriate personal protective equipment.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Put on appropriate personal protective equipment.

Section 6. Accidental release measures

For emergency responders	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".
6.2 Environmental precautions	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).
6.3 Methods and materials for containment and cleaning up		
Methods for cleaning up	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Stop leak if without risk. Move containers from spill area. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Stop leak if without risk. Move containers from spill area. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	Stop leak if without risk. Move containers from spill area. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.

Section 7. Handling and storage

7.1 Precautions for safe handling

Protective measures	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Put on appropriate personal protective equipment (see Section 8).
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Put on appropriate personal protective equipment (see Section 8).
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	Put on appropriate personal protective equipment (see Section 8).
Advice on general occupational hygiene	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.

7.2 Conditions for safe storage, including any incompatibilities

: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Store in accordance with local regulations. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination. See Section 10 for incompatible materials before handling or use.
SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Store in accordance with local regulations. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination. See Section 10 for incompatible materials before handling or use.
SureGuide pSGLenti CRISPR Control Plasmid (Human)	Store in accordance with local regulations. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Keep container tightly closed and sealed until ready for use. Containers that have been

Section 7. Handling and storage

opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination. See Section 10 for incompatible materials before handling or use.

7.3 Specific end use(s)

Recommendations	:	SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Industrial applications, Professional applications.
		SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Industrial applications, Professional applications.
		SureGuide pSGLenti CRISPR Control Plasmid (Human)	Industrial applications, Professional applications.
Industrial sector specific solutions	:	SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Not applicable.
		SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Not applicable.
		SureGuide pSGLenti CRISPR Control Plasmid (Human)	Not applicable.

Section 8. Exposure controls/personal protection

8.1 Control parameters

Occupational exposure limits

Ingredient name	Exposure limits
None.	

8.2 Exposure controls

Appropriate engineering controls	:	Good general ventilation should be sufficient to control worker exposure to airborne contaminants.
Environmental exposure controls	:	Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.

Individual protection measures

Hygiene measures	:	Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.
Eye/face protection	:	Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: safety glasses with side-shields.
Skin protection		
Hand protection	:	Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.
Body protection	:	Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.

Section 8. Exposure controls/personal protection

- Other skin protection** : Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.
- Respiratory protection** : Based on the hazard and potential for exposure, select a respirator that meets the appropriate standard or certification. Respirators must be used according to a respiratory protection program to ensure proper fitting, training, and other important aspects of use.

Section 9. Physical and chemical properties

9.1 Information on basic physical and chemical properties

Appearance

- Physical state** : SureGuide pSGLenti GeCKO v2.0 Liquid.
Library HuEx A
SureGuide pSGLenti GeCKO v2.0 Liquid.
Library HuEx B
SureGuide pSGLenti CRISPR Liquid.
Control Plasmid (Human)
- Color** : SureGuide pSGLenti GeCKO v2.0 Not available.
Library HuEx A
SureGuide pSGLenti GeCKO v2.0 Not available.
Library HuEx B
SureGuide pSGLenti CRISPR Not available.
Control Plasmid (Human)
- Odor** : SureGuide pSGLenti GeCKO v2.0 Not available.
Library HuEx A
SureGuide pSGLenti GeCKO v2.0 Not available.
Library HuEx B
SureGuide pSGLenti CRISPR Not available.
Control Plasmid (Human)
- Odor threshold** : SureGuide pSGLenti GeCKO v2.0 Not available.
Library HuEx A
SureGuide pSGLenti GeCKO v2.0 Not available.
Library HuEx B
SureGuide pSGLenti CRISPR Not available.
Control Plasmid (Human)
- pH** : SureGuide pSGLenti GeCKO v2.0 7
Library HuEx A
SureGuide pSGLenti GeCKO v2.0 7
Library HuEx B
SureGuide pSGLenti CRISPR 7
Control Plasmid (Human)
- Melting point** : SureGuide pSGLenti GeCKO v2.0 0°C (32°F)
Library HuEx A
SureGuide pSGLenti GeCKO v2.0 0°C (32°F)
Library HuEx B
SureGuide pSGLenti CRISPR 0°C (32°F)
Control Plasmid (Human)
- Boiling point** : SureGuide pSGLenti GeCKO v2.0 100°C (212°F)
Library HuEx A
SureGuide pSGLenti GeCKO v2.0 100°C (212°F)
Library HuEx B
SureGuide pSGLenti CRISPR 100°C (212°F)
Control Plasmid (Human)

Section 9. Physical and chemical properties

Flash point	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A SureGuide pSGLenti GeCKO v2.0 Library HuEx B SureGuide pSGLenti CRISPR Control Plasmid (Human)	Not available. Not available. Not available.
Evaporation rate	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A SureGuide pSGLenti GeCKO v2.0 Library HuEx B SureGuide pSGLenti CRISPR Control Plasmid (Human)	Not available. Not available. Not available.
Flammability (solid, gas)	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A SureGuide pSGLenti GeCKO v2.0 Library HuEx B SureGuide pSGLenti CRISPR Control Plasmid (Human)	Not applicable. Not applicable. Not applicable.
Lower and upper explosive (flammable) limits	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A SureGuide pSGLenti GeCKO v2.0 Library HuEx B SureGuide pSGLenti CRISPR Control Plasmid (Human)	Not available. Not available. Not available.
Vapor pressure	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A SureGuide pSGLenti GeCKO v2.0 Library HuEx B SureGuide pSGLenti CRISPR Control Plasmid (Human)	Not available. Not available. Not available.
Vapor density	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A SureGuide pSGLenti GeCKO v2.0 Library HuEx B SureGuide pSGLenti CRISPR Control Plasmid (Human)	Not available. Not available. Not available.
Relative density	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A SureGuide pSGLenti GeCKO v2.0 Library HuEx B SureGuide pSGLenti CRISPR Control Plasmid (Human)	Not available. Not available. Not available.
Solubility	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A SureGuide pSGLenti GeCKO v2.0 Library HuEx B SureGuide pSGLenti CRISPR Control Plasmid (Human)	Easily soluble in the following materials: cold water and hot water. Easily soluble in the following materials: cold water and hot water. Easily soluble in the following materials: cold water and hot water.
Partition coefficient: n-octanol/water	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A SureGuide pSGLenti GeCKO v2.0 Library HuEx B SureGuide pSGLenti CRISPR Control Plasmid (Human)	Not available. Not available. Not available.

Section 9. Physical and chemical properties

Auto-ignition temperature	SureGuide pSGLenti GeCKO v2.0	Not available.
	Library HuEx A	
	SureGuide pSGLenti GeCKO v2.0	Not available.
	Library HuEx B	
Decomposition temperature	SureGuide pSGLenti CRISPR	Not available.
	Control Plasmid (Human)	
	SureGuide pSGLenti GeCKO v2.0	Not available.
	Library HuEx A	
Viscosity	SureGuide pSGLenti GeCKO v2.0	Not available.
	Library HuEx A	
	SureGuide pSGLenti GeCKO v2.0	Not available.
	Library HuEx B	
	SureGuide pSGLenti CRISPR	Not available.
	Control Plasmid (Human)	

Section 10. Stability and reactivity

10.1 Reactivity	SureGuide pSGLenti GeCKO v2.0	No specific test data related to reactivity available for this product or its ingredients.
	Library HuEx A	
	SureGuide pSGLenti GeCKO v2.0	No specific test data related to reactivity available for this product or its ingredients.
	Library HuEx B	
10.2 Chemical stability	SureGuide pSGLenti CRISPR	No specific test data related to reactivity available for this product or its ingredients.
	Control Plasmid (Human)	
	SureGuide pSGLenti GeCKO v2.0	The product is stable.
	Library HuEx A	
10.3 Possibility of hazardous reactions	SureGuide pSGLenti GeCKO v2.0	The product is stable.
	Library HuEx A	
	SureGuide pSGLenti GeCKO v2.0	The product is stable.
	Library HuEx B	
10.4 Conditions to avoid	SureGuide pSGLenti CRISPR	The product is stable.
	Control Plasmid (Human)	
	SureGuide pSGLenti GeCKO v2.0	Under normal conditions of storage and use, hazardous reactions will not occur.
	Library HuEx A	
10.5 Incompatible materials	SureGuide pSGLenti GeCKO v2.0	Under normal conditions of storage and use, hazardous reactions will not occur.
	Library HuEx A	
	SureGuide pSGLenti GeCKO v2.0	Under normal conditions of storage and use, hazardous reactions will not occur.
	Library HuEx B	
	SureGuide pSGLenti CRISPR	Under normal conditions of storage and use, hazardous reactions will not occur.
	Control Plasmid (Human)	
	SureGuide pSGLenti GeCKO v2.0	No specific data.
	Library HuEx A	
	SureGuide pSGLenti GeCKO v2.0	No specific data.
	Library HuEx B	
	SureGuide pSGLenti CRISPR	No specific data.
	Control Plasmid (Human)	
	SureGuide pSGLenti GeCKO v2.0	May react or be incompatible with oxidizing materials.
	Library HuEx A	
	SureGuide pSGLenti GeCKO v2.0	May react or be incompatible with oxidizing materials.
	Library HuEx B	
	SureGuide pSGLenti CRISPR	May react or be incompatible with oxidizing materials.
	Control Plasmid (Human)	

Section 10. Stability and reactivity

10.6 Hazardous decomposition products	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Under normal conditions of storage and use, hazardous decomposition products should not be produced.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Under normal conditions of storage and use, hazardous decomposition products should not be produced.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	Under normal conditions of storage and use, hazardous decomposition products should not be produced.

Section 11. Toxicological information

11.1 Information on toxicological effects

Acute toxicity

Not available.

Irritation/Corrosion

Not available.

Sensitization

Not available.

Mutagenicity

Conclusion/Summary : Not available.

Carcinogenicity

Conclusion/Summary : Not available.

Reproductive toxicity

Conclusion/Summary : Not available.

Teratogenicity

Conclusion/Summary : Not available.

Specific target organ toxicity (single exposure)

Not available.

Specific target organ toxicity (repeated exposure)

Not available.

Aspiration hazard

Not available.

Information on the likely routes of exposure	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	Not available.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	Not available.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	Not available.

Potential acute health effects

Eye contact	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.

Section 11. Toxicological information

Inhalation	SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.
Skin contact	SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.
Ingestion	SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.

Symptoms related to the physical, chemical and toxicological characteristics

Eye contact	SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No specific data.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No specific data.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	No specific data.
Inhalation	SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No specific data.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No specific data.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	No specific data.
Skin contact	SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No specific data.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No specific data.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	No specific data.
Ingestion	SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No specific data.
	SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No specific data.
	SureGuide pSGLenti CRISPR Control Plasmid (Human)	No specific data.

Delayed and immediate effects and also chronic effects from short and long term exposure

Short term exposure

Potential immediate effects : Not available.

Potential delayed effects : Not available.

Long term exposure

Potential immediate effects : Not available.

Potential delayed effects : Not available.

Section 11. Toxicological information

Potential chronic health effects

General	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.
Carcinogenicity	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.
Mutagenicity	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.
Teratogenicity	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.
Developmental effects	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.
Fertility effects	: SureGuide pSGLenti GeCKO v2.0 Library HuEx A	No known significant effects or critical hazards.
	: SureGuide pSGLenti GeCKO v2.0 Library HuEx B	No known significant effects or critical hazards.
	: SureGuide pSGLenti CRISPR Control Plasmid (Human)	No known significant effects or critical hazards.

Numerical measures of toxicity

Acute toxicity estimates

Not available.

Section 12. Ecological information

12.1 Toxicity

Not available.

12.2 Persistence and degradability

Not available.

12.3 Bioaccumulative potential

Section 12. Ecological information

Not available.

12.4 Mobility in soil

Soil/water partition coefficient (K_{oc}) : Not available.

12.5 Other adverse effects : No known significant effects or critical hazards.

Section 13. Disposal considerations

13.1 Waste treatment methods

Disposal methods : The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Empty containers or liners may retain some product residues. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

Disposal should be in accordance with applicable regional, national and local laws and regulations. Local regulations may be more stringent than regional or national requirements.

The information presented below only applies to the material as supplied. The identification based on characteristic(s) or listing may not apply if the material has been used or otherwise contaminated. It is the responsibility of the waste generator to determine the toxicity and physical properties of the material generated to determine the proper waste identification and disposal methods in compliance with applicable regulations.

Refer to Section 7: HANDLING AND STORAGE and Section 8: EXPOSURE CONTROLS/PERSONAL PROTECTION for additional handling information and protection of employees.

Section 14. Transport information

DOT / TDG / Mexico / IMDG / IATA : Not regulated.

Special precautions for user : **Transport within user's premises:** always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

Transport in bulk according to Annex II of MARPOL and the IBC Code : Not available.

Section 15. Regulatory information

15.1 Safety, health and environmental regulations/legislation specific for the substance or mixture

U.S. Federal regulations : TSCA 8(a) CDR Exempt/Partial exemption: Not determined
Clean Water Act (CWA) 311: Edetic acid

Section 15. Regulatory information

Clean Air Act Section 112 : Not listed

(b) Hazardous Air Pollutants (HAPs)

Clean Air Act Section 602 : Not listed

Class I Substances

Clean Air Act Section 602 : Not listed

Class II Substances

DEA List I Chemicals : Not listed

(Precursor Chemicals)

DEA List II Chemicals : Not listed

(Essential Chemicals)

SARA 302/304

Composition/information on ingredients

No products were found.

SARA 304 RQ : Not applicable.

SARA 311/312

Classification : SureGuide pSGLenti GeCKO v2.0 Library HuEx A Not applicable.
 SureGuide pSGLenti GeCKO v2.0 Library HuEx B Not applicable.
 SureGuide pSGLenti CRISPR Control Plasmid (Human) Not applicable.

Composition/information on ingredients

No products were found.

State regulations

Massachusetts : None of the components are listed.

New York : None of the components are listed.

New Jersey : None of the components are listed.

Pennsylvania : None of the components are listed.

International regulations

Chemical Weapon Convention List Schedules I, II & III Chemicals

Not listed.

Montreal Protocol (Annexes A, B, C, E)

Not listed.

Stockholm Convention on Persistent Organic Pollutants

Not listed.

Rotterdam Convention on Prior Informed Consent (PIC)

Not listed.

UNECE Aarhus Protocol on POPs and Heavy Metals

Not listed.

Inventory list

Australia : Not determined.

Canada : Not determined.

China : All components are listed or exempted.

Section 15. Regulatory information

Europe	: All components are listed or exempted.
Japan	: <input checked="" type="checkbox"/> Japan inventory (ENCS) : Not determined. Japan inventory (ISHL) : All components are listed or exempted.
Malaysia	: Not determined.
New Zealand	: <input checked="" type="checkbox"/> Not determined.
Philippines	: <input checked="" type="checkbox"/> Not determined.
Republic of Korea	: <input checked="" type="checkbox"/> Not determined.
Taiwan	: All components are listed or exempted.
Thailand	: <input checked="" type="checkbox"/> Not determined.
Turkey	: Not determined.
United States	: All components are listed or exempted.
Viet Nam	: <input checked="" type="checkbox"/> Not determined.

Section 16. Other information

History

Date of issue	: 11/22/2018
Date of previous issue	: 09/14/2016
Version	: 2

Procedure used to derive the classification

Classification	Justification
Not classified.	

Indicates information that has changed from previously issued version.

Notice to reader

Disclaimer: The information contained in this document is based on Agilent's state of knowledge at the time of preparation. No warranty as to its accurateness, completeness or suitability for a particular purpose is expressed or implied.